Parish of Calcasieu • 5400 E. Broad Street • Lake Charles, LA 70615 Phone (337) 491-3700 • Fax (337) 494-4522

April 30, 2021

ADDENDUM #1

Training Academy Bldgs. 1, 2, and 4 (Asset #003-001)

NOTE: The following clarifications, changes, additions or deletions to the Specifications shall hereby be incorporated into the Contract Documents for the above referenced project. This addendum supersedes all contrary and conflicting information contained in previous Addenda, Drawings and Specifications and are hereby amended. Bidders shall acknowledge receipt of all Addenda in the space on the Bid Form.

PAINT TO MATCH - All Interior and Exterior Colors

BUILDING ONE

- 1. Remove and replace the existing (6'-0" x 7'-0") hollow metal door. Please note all existing door hardware-including locksets-to be detached and re-installed as indicated. No keying required.
- 2. N/A Trim is part of exterior metal wall package.
- 3. Remove and replace (3) hollow metal doors. (1) with side light-(2) without side light.
- 4. Please note all existing door hardware-including locksets-to be detached and re-installed as indicated. No keying required.
- 5. N/A Trim is part of exterior metal wall package.
- 6. Final Cleaning SF for Building 1-2 and Hallway between. See attached sketch with estimated dimensions. Contractors must verify SF to their satisfaction prior to bidding.
- 7. Clean floor Strip and Wax SF for Building 1-2 and Hallway between. See attached sketch with estimated dimensions. Contractors must verify SF to their satisfaction prior to bidding.
- 8. Existing Ceiling tile is Armstrong 861 All other replacement tile

BUILDING TWO

- 9. N/A Trim is part of exterior metal wall package.
- 10. Final Cleaning SF for Building 1-2 and Hallway between. See attached sketch with estimated dimensions. Contractors must verify SF to their satisfaction prior to bidding. Do not include the following rooms in BLD 1: Storage Area Right, Gun Storage, and Ammo.
- 11. Clean floor Strip and Wax SF for Building 1-2 and Hallway between. See attached sketch with estimated dimensions. Contractors must verify SF to their satisfaction prior to bidding.
- 12. New windows to meet 2018 Energy Code.
- 13. Level 5 Finish for new drywall finish to prep for new paint.
- 14. Sheriff's Department will detach and reset TV brackets.
- 15. Match existing material thickness.
- 16. Detach and reset casing $-2\frac{1}{4}$ ". See sketch
- 17. Finish Chair rail- 1 coat urethane.
- 18. Detach & reset Baseboard.
- 19. Exist Ceiling Tile is Armstrong 7710 Women's Restroom Only

All other ceiling tile - Armstrong 861

BUILDING FOUR

- 20. Demolish Building 4. Contractor to coordinate with Entergy after filing appropriate permit with the city Lake Charles Permit Dept.
- 21. Does the existing slab remain after modular building and foundations are removed? Yes.
- 22. Contractor will cap existing sanitary sewer and water main service at grade. Contractor will coordinate with Sheriff's office for water shut down coordination.

EXTERIOR:

FRONT ENTRY GATE	
Chain link fence gate - rolling - Detach & reset	30.00 LF
Reset and adjust	
Reset front access control pole	
PERIMETER FENCE	
R&R Chain link fence w/posts & top rail - 6' high - 9 gauge	180.00 LF
Replace damaged fence, west side property	
Wood fence 5' - 6' high - Detach & reset - per 8' section	47.00 EA
R&R Post - 2 3/8" diameter metal - 6' high fence	48.00 EA

Remove/Reset /Replace loose, bent and dislodged fence post

GENERATOR-SEPTIC FENCE

R&R Chain link fence w/posts & top rail - 6' high - 9 gauge R&R Chain link fence gate - 6' high - swinging

90.00 LF 16.00 LF

INSURANCE REQUIREMENTS: In addition to the insurance requirements listed in the request for quotes document, The CONTRACTOR shall maintain Builder's Risk coverage in the amount of the construction cost or in the amount of \$35,000.00, whichever is greater. Such coverage must include protection against named windstorm and flood. The Builder's Risk policy must allow for the OWNER to occupy the building during construction.

An additional bid walk will be held May 7, 2021 @ 9:00 AM

SUMMARY OF WORK

A. Project Summary:

Calcasieu Parish Sheriffs Training Academy 3958 Mallard Cove Drive Lake Charles, LA 70615

CPSO Training Academy Main Bldg. Main Classroom Interior Rebuild (003-001)

The Owner/Agent authorizes the following Scope of Work to be performed:

Exterior Building One


	Front Doors		
1	R&R Exterior door - Deluxe grade - wood w/detail - pre-hung RAR EXT, DooR - HOLLOW METAL	1.00 EA	
	Door closer - Commercial grade - Detach & reset	2.00 EA	
	Lockset - Commercial grade - Detach & reset	2.00 EA	
	Paint door/window trim & jamb - 2 coats (per side)	2.00 EA	
	Paint door slab only - 2 coats (per side)	2.00 EA	
2	R&R Wrap wood door frame & trim with aluminum (PER LF) RPR ALUMINUM/METAL WALL TRIM *Right Door*	19.00 LF	
3	R&R Steel door, 3' x 7' - with glass lite RAR Steel DOOR 3' x 7' - NO GLASS LIGHT	3.00 EA	1.00 EA 2.00 EA
	Door closer - Commercial grade - Detach & reset	3.00 EA	2.00 2.11
H	Lockset - Commercial grade - Detach & reset	3.00 EA	STATE OF THE STATE
	Paint door/window trim & jamb - 2 coats (per side)	6.00 EA	
	Paint door slab only - 2 coats (per side)	6.00 EA	
5	R&R Wrap wood door frame & trim with aluminum (PER LF) ROR ALUMINUM / METAL WALL TRIM *HVC Repairs*	51.00 LF	
	Comb and straighten a/c condenser fins	5.00 EA	

Contractor is responsible to field verify all dimensions and penetrations.

Contractor is responsible to field verify all dimensions and penetrations.

	Interior Building One					
6	Final cleaning - construction - Commercial		SF			
7	Clean floor, strip & wax all applicable floors	_	SF			
,	*Hallway between Left and Right* Clean suspended ceiling grid	109.56 SF				
%	Suspended ceiling tile - High grade - 2' x 4'	109.56 SF		TYPE	ARM 5 7R	0N6
	Exterior Building Two				861	
	Front Elevation					
9	R&R Wrap wood door frame & trim with aluminum (PER LF) RPR ALUMINUM METAL WALL TRIM *HVC Repairs*	24.00 LF				
	Comb and straighten a/c condenser fins	2.00 EA				
	Remove and Replace Aluminum window, horiz. slider 12-23 sf (2 pane)	7.00 EA				
	Interior Building Two					
D	Final cleaning - construction - Commercial		SF			
(1	Clean floor, strip & wax all applicable floors		SF			
	Storage Area/Room					
	Clean suspended ceiling grid	74.67 SF				
	Suspended ceiling tile - High grade - 2' x 4'	74.67 SF				
	HVAC					
	Clean suspended ceiling grid	71.33 SF				
	Suspended ceiling tile - High grade - 2' x 4'	71.33 SF				
	Classroom					
	Suspended ceiling tile - High grade - 2' x 4'	2650.81 SF				
	Suspended ceiling grid - 2' x 4'	2650.81 SF	V	12019	37	
12	Since the Hurricane shutters are not being replaced, and the windows will be thicker to meet current code. The interior trim will need replaced and modified to accept the thicker windows.	>—		WHAT	CODE CODE SY COD	AND
	R&R Window sill	98.00 LF	É	CNEKC	sy cod	B
	Stain & finish wood window sill	98,00 LF				

South WALL	R&R 5/8" drywall - hung, taped, floated, ready for paint WHAT LEVEL OF FINISH 4/5?	98.00 LF		
14	TV Brackets - Wall or ceiling mounted - Detach & reset Seal/prime then paint the walls (2 coats)	595.00 SF 4.00 EA	VERIFY ON LOCATION	DRAWING
15	R&R Bead board - 1/4" to 3/8" hardwood REPLACE WITH MATERIAL OF SAME Detach & Reset Casing - 2 1/4" hardwood	2183.69 SF THICKA 219.75 SF	VERIFY ON LOCATION	BRAWING
17	Finish chair rail - 1 coat urethane	74.00 LF 74.00 LF		
13	Detach & Reset Baseboard - 3 1/4"	74.00 LF	11	
	Classroom Entry	272.96 LF		
	Suspended ceiling tile - High grade - 2' x 4' Suspended ceiling grid - 2' x 4'	104.42 SF		
	Classroom Closet 1 Suspended ceiling tile - High grade - 2' x 4'	104.42 SF		
	Suspended ceiling grid - 2' x 4'	34.01 SF		
	Women's Bathroom Clean suspended ceiling grid	34.01 SF 130.90 SF		
19	Suspended ceiling tile - High grade - 2' x 4'	130.90 SF	ARMSTRONG	77/0
	Building Four			
20	Demolish/remove (2001 sf - 3000 sf) DOES EXISTING SLAB REMAIN? Y25 END SCOPE OF WO	CAP OF	- COOKING ERVICE AND FOF WATE	METER METER L OSEWER
	Contractor is responsible to field verify	MOORA	Y CONTRAC INATION O OFF netrations.	F WATER



Interior Of Main Building

⇒> ≥≥

